

SF61B SCANNER

Accessories Guide



Honeywell

TABLE OF CONTENTS

- 2 Holders and Chargers
- 3 Wearables
- 3 Battery and Cables



HOLDERS AND CHARGERS



SF61-UPK-S001

USB Charger, Single Bay

Charge a single SF61B mobility scanner via a USB port. (Requires a minimum 5V power source.)

Note: Not backward compatible with SF51.



871-221-001

Charge Cradle, Single Bay

Charge cradle accommodates a single SF61B or SF51 mobility scanner. Includes a mounting plate for fixed-mounting onto a countertop or wall. Separate power supply (851-089-306) must be purchased separately.

Note: Backward compatible with SF51.



213-007-001

FlexDock Cup, Dual Charge

Supports the charging of two SF61B scanners when snapped into the bay of a FlexDock base (852-918-002) – ordered separately.

Note: Not backward compatible with SF51.



852-918-002

FlexDock Base, Dual Charge

Provides two bays for charging. When combined with the FlexDock dual-charge cup above, this base can support the simultaneous charging of up to four SF61B mobility scanners. FlexDock cups, power supply (851-095-121), and country-specific line cord must be ordered separately.

Note: Not backward compatible with SF51.



DX2A28820

FlexDock Kit, Quad Charge

This comprehensive charge kit includes: two SF61B FlexDock cups, a FlexDock dual charge base, and a universal power supply. Must order country-specific line cord separately.

Note: Not backward compatible with SF51.



SF61-APK-S001

AC Charger, Single Bay

Charge a single SF61B mobility scanner. Must order country-specific line cords separately.

Note: Not backward compatible with SF51.



SF61-VPK-S001

Vehicle Power Adapter Kit

Includes a scanner holder, cable, and 12V DC power socket for connecting to your vehicle's power accessory (cigarette lighter) port. Charges a single scanner.

Note: Not backward compatible with SF51.

WEARABLES



SF61-MAG-S001

Magnet End-Cap and Belt Loop

This two-piece kit secures the scanner to your belt with magnetic force. Simply attach the belt loop with magnet to your belt, and affix the magnetic end-cap to the SF61B mobile scanner. This provides a quick and convenient attach/release method. A small plastic tool is included for installation/removal.

Note: Not backward compatible with SF51.



SF61-RIN-S001

Ring End-Cap and Wrist Strap

This two-piece kit includes an end-cap with ring that affixes to the SF61B mobile scanner, and a convenient wrist strap with cord-tightener. Simply thread the wrist strap through the ring, and the scanner can be conveniently worn around your wrist or arm – yet easily stowed away when both hands are needed. A small plastic tool is included for installation/removal.

Note: Not backward compatible with SF51.

BATTERY AND CABLES



SF61-BAT-S001

Spare Battery

To extend the long-term service life of the scanner, this 2,600 mAh spare battery can be installed in the field.

Note: Not backward compatible with SF51.



50129407-001

Universal Power Supply

This 5V DC power supply provides scanner power for use when host device power alone is insufficient. Includes ferrite (level VI). Must order country-specific line cords separately.

Note: Backward compatible with SF51.

For more information

www.honeywellaidc.com

Honeywell Safety and Productivity Solutions

9680 Old Bailes Road
Fort Mill, SC 29707
800-582-4263
www.honeywell.com